



# Valdez Operations Overview



**Prince William Sound Regional Citizens' Advisory Council Board Meeting**

May 04, 2023



# VMT Operations

	<b>2023</b>
Tankers Loaded	57
Tankers Escorted	57
Barrels Loaded	43,641,221
	<b>Since Startup</b>
Tankers Loaded	23,343
Tankers Escorted	14,662
Barrels Loaded	17,831,394,070

Totals up to March 31, 2023

# Health, Safety, & Environment

<b>Safety (TAPS)</b>	<b>2023</b>
Days Away From Work Cases	0
Recordable Incident Rate %	0.20
<b>Environment (Valdez)</b>	<b>2023</b>
Spill Volume (Gallons)	2.07
Number of Spills	5

# Fishing Vessel Availability

End of 1st Quarter 2023

<b>Port</b>	<b>Tier 1</b>	<b>Tier 2</b>
Valdez	19	12
Cordova	21 + 8RR	106
Whittier	6	15
Seward	0	18
Homer	0	39
Kodiak	0	35
<b>TOTAL</b>	<b>54</b>	<b>225</b>

\* RR = Rapid Response

# 2023 Contingency Plan Activities

- Reviewing scope of revisions - 18 AAC 75, Article 4.
- Three Contingency Plans need to be rewritten.
  - VMT Contingency Plan expires in Nov. 2024.

# 2023 1st Quarter Training & Exercises Completed

- 2/8 Cordova Rapid Response Vessel Exercise
- 3/6 VALDEZ STAR Open Water Deployment
- 3/11 Otter Rehabilitation Responder Training
- 3/16 VMT IMT Exercise
- 3/31 – 4/2 Kodiak Fishing Vessel Training

# 2023 VMT/PWS 2Q Training & Exercises

- Spring 2023 Fishing Vessel Training
  - Kodiak 3/31 - 4/2
  - Homer 4/3 - 4/8
  - Seward 4/9 - 4/12
  - Whittier 4/13 - 4/17 with Non-Mechanical ORE on 4/17
  - Cordova 4/17 - 4/26 with Near Shore ORE on 4/19 & 4/20
  - Valdez 4/27 - 5/3 with Near Shore ORE on 5/3
- 4/22 International Bird Rescue Training with Bird Rehabilitation Demonstration Exercise
- 5/4 – 5/8, 5/11 – 5/14, & 5/19 – 5/22 Initial Response Training
- 5/16 – 5/18 Hilcorp PWS Tanker Exercise



# 2023 Valdez Major Maintenance

- Replace sulfuric acid tank with HDPE tank
- Tank 93 – Internal API653 Inspection
- Tank 93 – Annular Ring Replacement
- DAF Cell 5 & 6 – Repair and Coat
- Tank 8 – Isolate and Clean
- Berth 4 Header & TK-93 Branch Leg Ballast System Inspection
- VMT 48” Crude A & B Header ILI Inspection
- OSRB 5 – Arrived in PWS
- Allison Creek replacement – Construction
- 500-2 Reconditioning



# OSRB-5



May 04, 2023

Page 9 of 13



# Allison Creek New Build



May 04, 2023

Page 10 of 13

# 52-TK-4 Tank Replacement





# Internal Inspections





# Questions?

