

Valdez Operations Overview



Prince William Sound Regional Citizens' Advisory Council Board Meeting

January 25, 2024

This document is proprietary and the property of TAPS Owners. Its sole use is for Alyeska Pipeline Service Company ("Alyeska"), and the state and federal regulatory agencies with authority to view the information. It may not be used for commercial or any other use. Any other use must be expressly permitted in writing by Alyeska as Agent for TAPS Owners. This use restriction includes reproduction or redistribution of this document or any portion of this document.

VMT Operations

	2023
Tankers Loaded	216
Tankers Escorted	219
Barrels Loaded	164, 365, 514
	Since Startup
Tankers Loaded	23,502
Tankers Escorted	14,824**
Barrels Loaded	17,952,122,363

YTD as of December 31, 2023

**During his presentation on Jan. 25, Andres Morales noted the number of tankers escorted was incorrect on this slide. He verbally conveyed that the correct number was 17,824.

Health, Safety, & Environment

Safety (TAPS)	2023
Days Away From Work Cases	0
Recordable Incident Rate %	0.24
Environment (Valdez)	2023
Spill Volume (Gallons)	258.3
Number of Spills	12

Fishing Vessel Availability

Port	Tier 1	Tier 2
Valdez	24	11
Cordova	26 + 8RR	99
Whittier	7	16
Seward	0	26
Homer	0	45
Kodiak	0	40
TOTAL	65	237

* RR = Rapid Response

2023 4th Quarter Contingency Plan Activities

- Support Shippers on PWS C-Plan Amendment RFAI responses
- VMT C-Plan renewal submitted on 10/20/2023
 - Anticipated RFAI's Mid-March



2023 4rd Quarter Training & Exercises Completed

- 10/3 SCAT Training
- 10/4 Unannounced IMT Notification Exercise
- 10/4 VMT Functional Exercise
- 10/6 Emergency Tow and Tether Exercise
- 10/9 IWR Wildlife Training
- 10/27 VMT On Land Tactics
- 11/16 Valdez Rapid Response Vessel Exercise
- 12/13 Unannounced Personnel Decon Exercise
- 12/28 Unannounced QI Notification Exercise (After Hours)

2024 Valdez Major Maintenance

- 2024 BWT Triennial Inspection & Repair A Header & Berth 5
- B5 Foam System Transition
- VMT Excavation and Direct Inspection of VMT Relief Line
- ILI of A & B Header
- External Coating of Tank 54-TK-3 and 54-TK-4 (VMT-Crude)
- 500-2 Refurbishment

2024 BWT Triennial Inspection & Repair A Header & Berth 5



B5 Foam System Transition



OSRB-5



Allison Creek Replacement



Questions?

