



Valdez Operations Overview



Prince William Sound Regional Citizens' Advisory Council Board Meeting
May 5 – 6, 2022



VMT Operations

	2022
Tankers Loaded	54*
Tankers Escorted	62*
Barrels Loaded	42,344,501*
	Since Startup
Tankers Loaded	23,130
Tankers Escorted	14,456
Barrels Loaded	17,664,095,821

*Up to April 31, 2022

Health, Safety, & Environment

Valdez Operations

Safety	2022
Days Away From Work Cases	2
TAPS Combined Recordable Incident Rate %	1.04%
Environment	2022
Spill Volume (Gallons)	2.75
Number of Spills	3

COVID-19 Response & Prevention

Processes and procedures for personnel and facilities:

- Masks are optional on TAPS.
- Site specific isolation and evacuation plans
- Communication plan

Urban workforce back to 100% capacity:

- All offices are open
- Vaccinations and boosters continue to be provided to the TAPS Workforce
 - 59.8% of TAPS Workforce.
 - Company goal of 65% of TAPS Workforce.

Fishing Vessel Availability

1st Quarter 2022

Port	Tier 1	Tier 2
Valdez	16	16
Cordova	20, 6RR	100
Whittier	6	16
Seward	0	20
Homer	0	44
Kodiak	0	34
TOTAL	42	230

* RR = Rapid Response

2022 Contingency Plan Activities

- VMT ODPCP minor Amendment 2021-3 was published in January 2022.
- Article 4 changes were reviewed, and comments submitted in January 2022.
- PWS Tanker ODPCP & SV-140 were renewed and published in February 2022.

1st Quarter 2022 – VMT / PWS Training & Exercises

- Emergency Tow and Tethered Escort Exercise
- Unannounced Rapid Response Vessel Call-out Exercise; Cordova
- 2022 VMT Equipment Deployment #1
- Alyeska IMT Training Exercise with Response Community, 3/2 & 3/3
- Wildlife Training in Homer, 3/29 – 3/31
- 2022 Spring Fishing Vessel Training, 3/31 – 5/5

Upcoming 2022 VMT/PWS Training & Exercises

Training/Exercise	Date(s)
IRT Training	5/11 – 5/15 5/20 – 5/23 5/26 – 5/29 6/1 – 6/5
Crowley PWS Tanker Exercise and Deployment	5/17 – 5/19
2022 Fall Fishing Vessel Training – Cordova	Late September
VMT Tabletop with Equipment Deployment #2	10/12

2022 Valdez Projects

- Replace sulfuric acid tank with HDPE tank
- Tank 93 - Internal API653 Inspection
- Tank 94 - Internal API653 Inspection
- Tank 54-TK-2 – Internal API653 Inspection
- Tank 54-TK-13 – External Coating
- West BTT - Repair and Coat
- OSRB 5 (Mineral Creek)- Construction
- ECO Escort Tug, Commander – Dry Dock



52-TK-4 Tank Replacement



May 5 - 6, 2022

Page 10 of 12


Internal Inspections



May 5 - 6, 2022

Page 11 of 12

ECO Escort Tug, Commander - Drydock



May 5 - 6, 2022

Page 12 of 12

OSRB5 – Started Construction



May 5 - 6, 2022

Page 13 of 12

VMT Tank Snow Removal

- Event
- Mitigations and Repairs
- RCAC Input



May 5 - 6, 2022

Page 14 of 12

VMT- Pressure Sensors

- Pressure Sensors- ETF
- 4 damaged sensors
- Currently isolated
- Under review



May 5 - 6, 2022

Page 15 of 12



Questions?



May 5 - 6, 2022

Page 16 of 12

16