



Valdez Operations Overview



Prince William Sound Regional Citizens' Advisory Council Board Meeting
January 26, 2023



VMT Operations

	2022
Tankers Loaded	202
Tankers Escorted	211
Barrels Loaded	176,446,377
	Since Startup
Tankers Loaded	23,286
Tankers Escorted	14,605
Barrels Loaded	18,539,689,449

Totals up to December 31, 2022

Health, Safety, & Environment

Safety (TAPS)	2022
Days Away From Work Cases	3
Recordable Incident Rate %	0.68
Environment (Valdez)	2022
Spill Volume (Gallons)	7.8
Number of Spills	6

Fishing Vessel Availability

End of 4th Quarter 2022

Port	Tier 1	Tier 2
Valdez	20	16
Cordova	22 + 7RR	106
Whittier	6	14
Seward	0	24
Homer	0	37
Kodiak	0	34
TOTAL	55	231

* RR = Rapid Response

2022 Contingency Plan Activities

- VMT Contingency Plan Minor Amendment 2022-1:
Published December 2022.
- PWS Tanker Contingency Plan Minor Amendment:
Published December 2022.

2022 4th Quarter Training & Exercises Completed

- VMT IMT Exercise 10/11 – 10/12
- Wildlife Training
 - Valdez 10/17 - 10/19
 - Cordova 10/19 - 10/21
- Nearshore Open Readiness Exercise (ORE)
 - Nelson Bay 11/3
- Unannounced Decontamination Exercise 12/7

2023 Contingency Plan Activities

- 18 AAC 75, Article 4

2023 VMT/PWS Upcoming Training & Exercises

- 3/23 VMT IMT Training Exercise
- 4/20 2023 VMT Wildlife Equipment Deployment
- 5/16 PWS IMT Exercise - Hilcorp
- 10/3 SCAT Training
- 10/4 VMT IMT Exercise
- Spring Fishing Vessel Training
 - Kodiak 3/29 – 4/2
 - Homer 4/3 – 4/8
 - Seward 4/9 – 4/12
 - Whittier 4/13 – 4/17
 - Cordova 4/17 – 4/26
 - Valdez 4/27 – 5/3

2023 VMT Snow Removal

- Tank Pressure Vacuum Vents (PVV) Repairs
 - 3 tank nozzles fitted with encapsulation assembly
 - 3 tank nozzles fitted with blind flange
 - All other PVVs repaired
 - Tank 2 return to service
- Snow Removal Updates
 - Policies and Procedures (priorities, practices)
 - Monitoring and reporting
 - Staffing Plan

2023 Valdez Major Maintenance

- Replace sulfuric acid tank with HDPE tank
- Tank 93 – Internal API653 Inspection
- Tank 93 – Annular Ring Replacement
- DAF Cell 6 – Repair and Coat
- Tank 8 – Isolate, Clean and Remove from Service
- Berth 4 Header & TK-93 Branch Leg Ballast System Inspection
- VMT 48” Crude A & B Header ILI Inspection
- OSRB 5 (Mineral Creek) – Construction
- 500-2 – Shipyard
- Allison Creek replacement - Construction

OSRB-5



January 26, 2023

OSRB-5



January 26, 2023

52-TK-4 Tank Replacement



January 26, 2023

Page 9 of 11



Internal Inspections



January 26, 2023

Page 10 of 11



Questions?

